

Honeywell

hereby appoints

Magnum Aviation Pvt. Ltd.

Kochi, Kerala, India

as an

Authorized Avionics Dealer

which meets the standards required to perform the following Service Categories:

- | | |
|---|--|
| 01 Silver Crown NAV/Comm/ADF/ILS/Audio/MKR Beacon Bench Repair | 15B Mark VI, Mark VIII, Mark XXII EGPWS Sys Troubleshoot to LRU |
| 01A Silver Crown Long Range NAV Bench Repair | 15C Mark VII GPWS System Troubleshoot to LRU |
| 01B Silver Crown GPS Long Range NAV Bench Repair | 15D TCAS II System Troubleshoot to LRU, ACAS |
| 01C Silver Crown GPS Long Range NAV System Install/Troubleshoot | 15E Data Recorders-SSFDR & SSCVR Sys Install/Troubleshoot to LRU |
| 02 Silver Crown Transponder/DME/RNAV Bench Repair | 20F FMS-2000 Flight Man. System, HT9000/9100-System
Install/Troubleshoot to LRU |
| 02A KT70/71 Mode S Transponder Bench Repair | 30 Epic CDS/R, EFIS, Lasers, HUD-2020, Multi-Channel Satcom,
Cabin Systems, Gyros, TAIS |
| 03 Primus II Radios System Install/Troubleshoot to LRU | 50 Single Engine and Light Twin NAV/COMM/Pulse |
| 03A Gold Crown NAV/Comm/ADF/ILS/Audio/MKR Beacon Bench Repair | 51 Heavy Twin and Turbine NAV/COMM/Pulse |
| 03B Gold Crown Long Range NAV Bench Repair | 52 Single Engine and Light Twin Safety Products |
| 03C Gold Crown High Frequency Bench Repair | 53 Heavy Twin and Turbine Safety Products |
| 04 Gold Crown Transponder/DME/RNAV Bench Repair | 54 Single Light Twin Autopilots |
| 04A MST 67A Mode S Transponder Bench Repair | 55 Heavy Twin Turbines Autopilots |
| 10C AA300, AM250 System Install/Troubleshoot to LRU | |
| 15A Mark V GPWS System Troubleshoot to LRU | |

The Avionics Dealership Authorization that underlies this appointment, and this certificate, are not transferable and will continue in effect until December 31, 2012 unless terminated, suspended or revoked.