



## **MAGNUM AVIATION PVT. LTD.**

Plot #68AC,NSEZ,Gautam Budh Nagar, Phase-II, Noida-201305 (U.P.) INDIA


FAA CERTIFICATE No. 6MGY507B

### **CAPABILITY LIST FOR REPAIR STATION**

**LIMITED RATINGS:**

<b>NAME OF LIMITED RATINGS</b>	<b>DESCRIPTION</b>	<b>SPECIFICATION</b>
NON DESTRUCTIVE INSPECTION TESTING AND PROCESSING (Limited Rating)	<b>MPI-</b> Magnetic Particle Inspection	ASTM-E1444 & MIL-I-6868E
	<b>ECI-</b> Eddy Current Inspection	As per CMM
	<b>FPI-</b> Fluorescent Penetrant Inspection	ASTM-E1417
	<b>UTI-</b> Ultra Sonic Inspection	As per CMM

Chief Inspector  
M/s Magnum Aviation Pvt. Ltd.



Rev 1  
Date: 23/12/2010

Page 1 of 3



# MAGNUM AVIATION PVT. LTD.

Plot #68AC,NSEZ,Gautam Budh Nagar, Phase-II, Noida-201305 (U.P.) INDIA


## FAA CERTIFICATE No. 6MGY507B CAPABILITY LIST FOR REPAIR STATION

### ACCESSORY RATING CLASS 1: AIRCRAFT WHEEL AND BRAKES

S/N	Manufacturer	Part Number	Description	Maintenance Limitation
01	Goodrich	3-1558	Main Wheel Assy	Inspection, Repair, Overhaul & Modification as per relevant CMM & FAA Regulatory requirements.
		3-1654	Main Wheel Assy	Inspection, Repair, Overhaul & Modification as per relevant CMM & FAA Regulatory requirements.
		3-1559	Nose Wheel Assy	Inspection, Repair, Overhaul & Modification as per relevant CMM & FAA Regulatory requirements.
		2-1587-1	Brake Assy	Inspection, Repair, Overhaul & Modification as per relevant CMM & FAA Regulatory requirements.
		3-1550-1	Main Wheel Assy	Inspection, Repair, Overhaul & Modification as per relevant CMM & FAA Regulatory requirements.
		3-1622	Nose Wheel Assy	Inspection, Repair, Overhaul & Modification as per relevant CMM & FAA Regulatory requirements.
		3-1582	Brake Assy	Inspection, Repair, Overhaul & Modification as per relevant CMM & FAA Regulatory requirements.
		3-1531-3	Nose Wheel Assy	Inspection, Repair, Overhaul & Modification as per relevant CMM & FAA Regulatory requirements.
02	MABS (ABSC)	90000582	Main Wheel Assy	Inspection, Repair, Overhaul & Modification as per relevant CMM & FAA Regulatory requirements.
		90000581 & 90000581-1	Nose Wheel Assy	Inspection, Repair, Overhaul & Modification as per relevant CMM & FAA Regulatory requirements.
		90000583-1, -2, -3/PR	Brake Assy	Inspection, Repair, Overhaul & Modification as per relevant CMM & FAA Regulatory requirements.
		5007996-1	Brake Assy	Inspection, Repair, Overhaul & Modification as per relevant CMM & FAA Regulatory requirements.
03	Messier Bugatti	C20195162	Main Wheel Assy	Inspection, Repair, Overhaul & Modification as per relevant CMM & FAA Regulatory requirements.
		C20225508,09,10	Brake Assy	Inspection, Repair, Overhaul & Modification as per relevant CMM & FAA Regulatory requirements.

Rev 1  
Date: 23/12/2010

Chief Inspector  
M/s Magnum Aviation Pvt. Ltd.



Page 2 of 3



## MAGNUM AVIATION PVT. LTD.

Plot #68AC,NSEZ,Gautam Budh Nagar, Phase-II, Noida-201305 (U.P.) INDIA

FAA CERTIFICATE No. 6MGY507B  
CAPABILITY LIST FOR REPAIR STATION

### ACCESSORY RATING CLASS 1: AIRCRAFT WHEEL AND BRAKES

S/N	Manufacturer	Part Number	Description	Maintenance Limitation
04	Honeywell	2612301-2	Main Wheel Assy.	Inspection, Repair, Overhaul & Modification as per relevant CMM & FAA Regulatory requirements.
		2607825-1,2	Nose Wheel Assy.	Inspection, Repair, Overhaul & Modification as per relevant CMM & FAA Regulatory requirements.
		2612302-1	Brake Assy.	Inspection, Repair, Overhaul & Modification as per relevant CMM & FAA Regulatory requirements.



The image shows a handwritten signature in blue ink to the left of a circular blue stamp. The stamp contains the text "MAGNUM AVIATION PVT. LTD." around the perimeter and "NOIDA" in the center, with a small star at the bottom.

Chief Inspector  
M/s Magnum Aviation Pvt. Ltd.

Rev 1  
Date: 23/12/2010

Page 3 of 3